

## Dosing monitor

The dosing monitor is used in connection with the dosing monitoring function of DME and DMS-A, AR pumps.

The monitor surveys the dosing process and sends a signal to the pump if an error occurs.

Materials in contact with liquid: PP/EPDM or PP/FKM.



GrA1033

Fig. 20 Dosing monitor

		DME/S 2	DME/S 4-19	DME 48	DME 60-150	DME 375-940
Maximum pressure	[bar]	10	10	10	10	10
Maximum liquid temperature	[°C]	50	50	50	50	50
Maximum liquid viscosity	[mPa s]	500	500	500	500 *)	500 *)

Kits for the dosing monitor:

Materials in contact with the liquid	DME/S 2	DME/S 4-19	DME 48	DME 60-150	DME 375-940
PP/E	96655210	96655216	96655218	96655230	96655232
PP/FKM	96655215	96655217	96655219	96655231	96655233